

Michaelson Connor and Boul

5312 Bolsa Ave., Suite 200, Huntington Beach, CA 92649

714-230-3600

Property Condition Report



Case Number: 263-389643B

Full Address: 2080 Jefferson Rd.
Harrison, MI 48625

Inspection Date: 02-28-2009

Inspection Type: Property Condition Inspection

Prepared By: Snow Enterprises, LLC

NOTICE TO ALL PROSPECTIVE PURCHASERS: Pursuant to section 5.3.4 of HUD RFP: R-OPC-22505, you are hereby notified that the contents of this inspection report are for information only and do not imply any guarantee or warranty of property condition.

Table of Contents

1	Inspection Requirements	1
	1.1 Exclusions of Inspections	1
	1.2 Exclusions and Limitations	1
2	Report Summary	2
3	Directions to Property	4
4	Property Information	4
5	Additional Comments	4
6	Structure	5
	6.1 General Structure Information	5
	6.2 Structure Checkpoints	5
	6.3 Structure Comments	5
7	Exterior	6
	7.1 General Exterior Information	6
	7.2 Exterior Checkpoints	6
	7.3 Exterior Comments	6
8	Roof	8
	8.1 General Roof Information	8
	8.2 Roof Checkpoints	8
	8.3 Roof Comments	8
9	Plumbing	9
	9.1 General Plumbing Information	9
	9.2 Plumbing Checkpoints	9
	9.3 Plumbing Comments	9
10	Electrical	11
	10.1 General Electrical Information	11
	10.2 Electrical Checkpoints	11
	10.3 Electrical Comments	11
11	HVAC	12
	11.1 General HVAC Information	12
	11.2 HVAC Checkpoints	12
	11.3 HVAC Comments	13
12	Interior	14
	12.1 General Interior Information	14
	12.2 Interior Checkpoints	14
	12.3 Interior Comments	14
13	Appliances	15
	13.1 General Appliances Information	15

Table of Contents (continued)

13.2	Appliances Checkpoints	15
13.3	Appliances Comments.....	15
14	HOA Information	16
15	Code Violations.....	16
16	Pending Litigation	16
17	Demo Orders.....	16
18	Radon Gas and Mold Notice and Release Agreement	17
19	Environmental Issues	18
20	Environmental Compliance Record, Attachment 18 in Handbook 4310.5.....	19

1. INSPECTION REQUIREMENTS

STRUCTURAL COMPONENTS including foundation, floors, walls, columns, ceilings, and roofs.

EXTERIOR OF STRUCTURE including wall claddings, entryway doors, decks, steps, eaves, driveways, windows, patios, pools/spas, lawns, landscape, retaining walls, sheds/outbuildings, and fences.

ROOFING including roof coverings, roof drainage systems, flashing, skylights, and chimneys.

PLUMBING including interior water supply and distribution system, interior waste drains and vent system, hot water system, fuel storage and distribution system, and sump pump.

ELECTRICAL including service entrance conductors, service equipment, main distribution panels, voltage ratings, a representative number of installed ceiling fans, lighting fixtures, switches and receptacles, ground fault circuit interrupters, and smoke detectors.

HVAC (Heating Ventilation, Air Conditioning) including permanently installed heating system and its controls, chimneys, heat distribution system, including fans, pumps, and ducts , and automatic safety controls.

Normal operating control of the central air conditioning system and the distribution system.

Insulation vapor barriers, ventilation of attic and foundation, kitchen, bathroom and laundry venting systems, and the operation of any readily accessible attic ventilation fan when temperature permits

INTERIOR including walls, ceilings, floors, steps, cabinets, doors, windows, etc

BUILT-IN KITCHEN APPLIANCES including the observation and operation of dishwasher, range, trash compactor, garbage disposal, ventilation equipment, permanently installed oven and microwave oven.

1.1. Exclusions of Inspection

1.2. Exclusions and Limitations

This inspection is limited to visual observations of apparent conditions existing at the time of the inspection only. This inspection is not intended to provide the purchaser with information regarding the advisability of this purchase, the market value of the property, the compliance or non-compliance with codes, ordinances and statutes, the suitability of this property for specialized use, the life expectancy of any component or system in the property, the presence or absence of pests or insects, or cosmetic or underground items or items that are not permanently installed. This inspection report does not address and is not intended to address the possible presence of any danger from any potentially harmful substance and environmental hazards, including but not limited to radon gas, lead paint, asbestos, urea formaldehyde (UFFI), toxic or chemical analysis, airborne hazards, polluted water, or underground oil tanks.

2 Report Summary

This summary is provided to highlight those findings that we believe are for information, significant in nature or which appear to be in immediate need of repair or a safety concern.

This inspection is visual only in areas that were accessible at the time of inspection. No dismantling of building components or systems, no destructive testing, no engineering functions, and no code compliance inspections were performed at the time of the inspection. The findings were as follows:

Structure

- Unit 2 is built on a slab This is the second unit of a duplex. All common issues are listed in the report for 263-389643.
- The checkpoints within the "Structure" area of the property condition report pertain to the foundation areas of the home. This includes slabs, crawlspaces, and basements. Information on Non-structural issues regarding floors, walls, and ceilings will be found on the "Interior" page of the report.

Exterior

- At the time of the inspection, the exterior of the unit was in acceptable condition with noted exceptions. This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

Roof

- There were no apparent deficiencies noted regarding the roof of the unit. This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

Plumbing

- The plumbing lines were checked using air pressure and no leaks were found.
- The plumbing system was in working condition at the time of inspection. The water lines and water heater are shared with unit 1 This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

Electrical

- The electrical system was functional with no noted deficiencies. A generator was used to test the systems. The electrical panel is in the basement of unit 1. This unit has no basement. This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

HVAC

- There is no heat source for this unit This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

Interior

- The interior of the structure was in satisfactory condition with noted exceptions.

Appliances

- The appliances present were in working condition at the time of the inspection.

3 Directions to Property

No Property Directions

4 Property Information

Address: 2080 Jefferson Rd., Harrison, MI 48625

Structure Age: See appr.

Access to Property: Hud Key

Number of Bathrooms: 1

Square Footage: 1001-1500 Sq. Ft.

Electric Status: Inactive

Water Status: Inactive

Gas Status: Inactive

Occupancy Status: No

5 Additional Comments

Power Company:

Meter Number:

Water Company:

Gas Company:

Meter Number:

6 Structure

This portion of the inspection covers general structural component checkpoints of the subject property such as foundation, floors, walls, columns, ceilings, basement, etc.

6.1 General Structure Information

Access Method: None
Basement Type: NA

Foundation Type: Slab

6.2 Structure Checkpoints

Checkpoint	Rating	Comment
Basement Floor:	NA	
Beam Supports:	NA	
Ceilings:	NA	
Cracks:	NV	
Crawlspace Door:	NA	
Floor:	NA	
Footing Drain:	NV	
Ground Grade:	S	
Insulation:	NA	
Joists:	NA	
Sill Plate:	NV	
Structural:	S	
Sub-Flooring:	NA	
Walls:	NA	
Wall/Ground Distance:	NA	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

6.3 Structure Comments

Unit 2 is built on a slab This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

The checkpoints within the "Structure" area of the property condition report pertain to the foundation areas of the home. This includes slabs, crawlspaces, and basements. Information on Non-structural issues regarding floors, walls, and ceilings will be found on the "Interior" page of the report.

7 Exterior

This portion of the inspection covers general exterior checkpoints of the subject property structure such as wall claddings, entryway doors, decks, steps, eaves, driveways, windows, patios, pools/spas, lawns, landscape, retaining walls, sheds/outbuildings, fences, etc.

7.1 General Exterior Information

Exterior Siding: Vinyl
Weather Conditions: Clear
Temperature: <30

Lot Size: Less than one-quarter
Wall Structure: Frame

7.2 Exterior Checkpoints

Checkpoint	Rating	Comment
Balconies:	NA	
Carpports:	NA	
Debris:	S	
Decks/Deck Steps:	NA	
Driveway:	S	
Eaves:	S	
Entry Locks:	S	
Exterior Door/Locks:	S	
Fencing/Gates:	NA	
Garage Door:	MR	The garage door is damaged and partially boarded.
Garage Door Opener:	S	
Landscape:	S	
Lawn Care:	S	
Leaf Removal:	S	
Patio:	NA	
Pool/Spa:	NA	
Porches:	NA	
Railings:	NA	
Retaining Walls:	NA	
Sheds and Outbuildings:	NA	
Sidewalks:	S	
Siding Condition:	S	
Snow Removal:	S	
Exterior Steps:	S	
Storm/Screen Windows:	S	
Storm/Screen Doors:	S	
Windows:	S	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

7.3 Exterior Comments

At the time of the inspection, the exterior of the unit was in acceptable condition with noted exceptions. This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

8 Roof

This portion of the inspection covers general exterior roofing component checkpoints of the subject property such as roof coverings (shingles, flashing, skylights, chimneys, etc.), structural elements of the roof (trusses, rafters, ceiling foists, etc.), roof drainage systems, etc.

8.1 General Roof Information

Roof Type: Gabled
Method to Observe Attic: None
Number of Layers: 1
Roofing Material: Asphalt

Gutter Type: Aluminum
Method to Observe Roof: Ladder
Attic Vent Type: Other

8.2 Roof Checkpoints

Checkpoint	Rating	Comment
Shingle Cond.:	S	
Flashing/Joints:	S	
Soffits/Fascias:	S	
Skylights:	NA	
Vent Pipes:	S	
Chimney:	NA	
Gutters:	S	
Downspouts:	S	
Attic Ventilation:	S	
Attic Water:	NV	
Attic Insulation:	NV	
*Structural Cond.:	S	
*Sheathing Cond.:	NV	
Truss:	S	The trusses are visible in the garage.
Roof Exhaust Fan(s):	NA	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

8.3 Roof Comments

There were no apparent deficiencies noted regarding the roof of the unit. This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

9 Plumbing

This portion of the inspection covers general plumbing checkpoints of the subject property such as interior water supply and distribution system, interior waste drains and vent system, hot water system, fuel storage and distribution system, and sump pump.

9.1 General Plumbing Information

Waste Disposal: Septic

WH Size: 40 Gallons

WH Model:

Water Piping: Mixed

Waste Piping: Combination

WH Manufacturer: Mor flo

Water Supply: Well

9.2 Plumbing Checkpoints

Checkpoint	Rating	Comment
Bar Sinks:	NA	
Bath Fixtures:	MG	There is a missing toilet seat and lid.
Connections:	S	The plumbing lines were checked using air pressure and no leaks were found.
Interior Spa/Hot Tub:	NA	
Interior Vent:	S	
Kitchen Sink:	S	
Laundry Tub:	NA	
Main Shut Off:	S	
Pressure Relief Valve:	S	
Pressure Tank:	S	
Septic Location:	NV	
Septic System:	NV	
Sewer Drainage:	NV	
Shower Pan:	S	
Sprinkler System:	NA	
Storage Tanks:	NA	
Vent System:	NA	
Water Filter:	S	
Water Heaters:	S	
Water Meter:	NA	
Water Softener:	MG	The water softener is missing
Water Supply:	S	
Well:	S	
Well Location:	S	
Well/Sump Pump:	NA	This unit has no sump pump.

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

9.3 Plumbing Comments

The plumbing system was in working condition at the time of inspection. The water lines and water heater are shared with unit 1 This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

10 Electrical

This portion of the inspection covers general electrical checkpoints of the subject property such as service entrance conductors, service equipment, main distribution panels, voltage ratings, a representative number of installed ceiling fans, lighting fixtures, switches and receptacles, ground fault circuit interruptors, smoke detectors, etc.

10.1 General Electrical Information

Additional Space Available: No

Capacity: 200A 120-240V

General Wiring: Good

Panel Manufacturer: Square D

Wiring: Copper

Box Location: Basement

Conductor Type: Aluminum

Num. of Disconnects: 2

Panel Type: Breaker

10.2 Electrical Checkpoints

Checkpoint	Rating	Comment
Appliance Wiring:	S	
Bath GFCI:	S	
Breaker Cond.:	S	
Exterior GFCI:	S	
Exterior Wiring:	S	
Ground/Bonding:	S	
HVAC Wiring:	S	
Interior Wiring:	S	
Kitchen GFCI:	S	
Lighting Fixtures:	S	
Panel Box:	S	
Rec. Location:	S	
Service Attach:	S	
Service Meter:	S	
Sub Panel Box:	S	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

10.3 Electrical Comments

The electrical system was functional with no noted deficiencies. A generator was used to test the systems. The electrical panel is in the basement of unit 1. This unit has no basement. This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

11 HVAC

This portion of the inspection covers general HVAC checkpoints of the subject property such as permanently installed heating system and its controls, chimneys, heat distribution system, including fans, pumps, and ducts, and automatic safety controls.

Normal operating control of the central air conditioning system and the distribution system, etc.

Insulation vapor barriers, ventilation of attic and foundation, kitchen, bathroom and laundry venting systems, and the operation of any readily accessible attic ventilation fan when temperature permits, etc.

11.1 General HVAC Information

Inside Unit Brand: NA

Inside Model No.: NA

Inside Unit Type: NA

Outside Unit Brand: NA

Outside Model No.: NA

Outside Unit Type: NA

11.2 HVAC Checkpoints

Checkpoint	Rating	Comment
A/C Component Cond.:	NA	
Boiler:	NA	
Coil:	NA	
Coil Fins:	NA	
Condens. Pipe:	NA	
Controls:	NA	
Draft Device:	NA	
Duct Work:	NA	
Electric Heat:	NA	
Evaporator:	NA	
Fans:	NA	
Filter:	NA	
Fireplace:	NA	
Flue Pipe/Draft:	NA	
Furnace System:	NA	No heat source could be located for this unit.
Gas Lines:	NA	
Heat Exchanger:	NA	
Heat Pump:	NA	
Inside Fan Motor:	NA	
Oil Tank:	NA	
Oil Tank Vent:	NA	
Refrigerant Line:	NA	
Supply Returns:	NA	
Temp. Drop Test:	NA	
Thermostat:	NA	
Vapor Barrier:	NA	
Ventilation:	NA	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

11.3 HVAC Comments

There is no heat source for this unit This is the second unit of a duplex. All common issues are listed in the report for 263-389643.

12 Interior

The interior portion of the inspection covers checkpoints involving the interior walls, ceilings, floors, steps, cabinets, doors, and windows.

12.1 General Interior Information

There are no general information points in this section.

12.2 Interior Checkpoints

Checkpoint	Rating	Comment
Cabinets:	MR	There are damaged kitchen cabinets.
Ceilings:	S	
Closets:	S	
Countertops:	S	
Interior Debris:	S	
Detectors:	S	
Door Hardware:	S	
Doors:	MR	There are damaged door jambs.
Dryer Vent:	S	
Floor:	MR	This property has soiled carpets and damaged flooring.
Mold:	NV	
Railings:	NA	
Stairwells:	NA	
Steps:	NA	
Walls:	S	
Windows:	S	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

12.3 Interior Comments

The interior of the structure was in satisfactory condition with noted exceptions.

13 Appliances

The kitchen appliance portion of the inspection covers checkpoints involving the observation and operation of the refrigerator, dishwasher, range, trash compactor, garbage disposal, ventilation equipment, microwave and any other permanently installed appliances.

13.1 General Appliances Information

There are no general information points in this section.

13.2 Appliances Checkpoints

Checkpoint	Rating	Comment
Dishwasher:	MG	The dishwasher is missing.
Disposal:	NA	The garbage disposal is not applicable.
Dryer:	MG	The dryer is missing.
Microwave:	NA	
Oven:	NA	
Range Hood:	NA	
Range/Stove:	S	
Refrigerator:	S	
Washer:	MG	The washing machine is missing.
Other:	NA	

Key: Y=Yes N=No S=Satisfactory U=Unsatisfactory MR=Marginal MG=Missing NA=Not Applicable NV=Not Visible

13.3 Appliances Comments

The appliances present were in working condition at the time of the inspection.

14 HOA Information

There were no signs, notices, placards or other indications of an HOA visible at the time of inspection.

15 Code Violations

There are no known code violations.

16 Pending Litigation

There is no known pending litigation.

17 Demo Orders

There are no known property demo orders.

18 – Radon Gas and Mold Notice and Release Agreement

U.S. Department of Housing and Urban Development
Office of Housing
Federal Housing Commissioner

Property Case #: 263-389643B
Property address: 2080 Jefferson Rd.
Harrison, MI 48625

PURCHASERS ARE HEREBY NOTIFIED AND UNDERSTAND THAT RADON GAS AND SOME MOLDS HAVE THE POTENTIAL TO CAUSE SERIOUS HEALTH PROBLEMS.

Purchaser acknowledges and accepts that the HUD-owned property described above (the “Property”) is being offered for sale “AS IS” with no representations as to the condition of the Property. The Secretary of the U.S. Department of Housing and Urban Development, his/her officers, employees, agents, successors and assigns (the “Seller”) and Michaelson Connor and Boul an independent management and marketing contractor (“M & M Contractor”) to the Seller, have no knowledge of radon or mold in, on, or around the Property other than what may have already been described on the web site of the Seller or M & M Contractor or otherwise made available to Purchaser by the Seller or M & M Contractor.

Radon is an invisible and odorless gaseous radioactive element. Mold is a general term for visible growth of fungus, whether it is visible directly or is visible when barriers, such as building components (for example, walls) or furnishings (for example, carpets), are removed.

Purchaser represents and warrants that Purchaser has not relied on the accuracy or completeness of any representations that have been made by the Seller and/or M & M Contractor as to the presence of radon or mold and that the Purchaser has not relied on the Seller’s or M & M Contractor’s failure to provide information regarding the presence or effects of any radon or mold found on the Property.

Real Estate Brokers and Agents are not generally qualified to advise purchasers on radon or mold treatment or its health and safety risks. **PURCHASERS ARE ENCOURAGED TO OBTAIN THE SERVICES OF A QUALIFIED AND EXPERIENCED PROFESSIONAL TO CONDUCT INSPECTIONS AND TESTS REGARDING RADON AND MOLD PRIOR TO CLOSING.** Purchasers are hereby notified and agree that they are solely responsible for any required remediation and/or resulting damages, including, but not limited to, any effects on health, due to radon or mold in, on or around the property.

In consideration of the sale of the Property to the undersigned Purchaser, Purchaser does hereby release, indemnify, hold harmless and forever discharge the Seller, as owner of the Property and separately, M & M Contractor, as the independent contractor responsible for maintaining and marketing the Property, and its officers, employees, agents, successors and assigns, from any and all claims, liabilities, or causes of action of any kind that the Purchaser may now have or at any time in the future may have against the Seller and/or M & M Contractor resulting from the presence of radon or mold in, on or around the Property.

Purchaser has been given the opportunity to review this Release Agreement with Purchaser’s attorney or other representatives of Purchaser’s choosing, and hereby acknowledges reading and understanding this Release. Purchaser also understands that the promises, representations and warranties made by Purchaser in this Release are a material inducement for Seller entering into the contract to sell the Property to Purchaser.

Dated this ____ day of _____, 20__.

Purchaser’s Signature

Purchaser’s Signature

Purchaser’s Printed Name

Purchaser’s Printed Name

19 Environmental Issues

There are no known property environmental issues.

**20 – ENVIRONMENTAL COMPLIANCE RECORD
SINGLE FAMILY PROPERTY DISPOSITION**

FHA Case Number: 263-389643B	
Property Address: 2080 Jefferson Rd., Harrison, MI 48625	
COMPLIANCE FINDINGS	SOURCE / DOCUMENTATION
<p>1. HISTORIC PRESERVATION Property <input type="checkbox"/> is <input type="checkbox"/> is not listed on the National Register of Historic Places.</p> <p>Property <input type="checkbox"/> is <input type="checkbox"/> is not located in an Historical District.</p> <p><i>Note: An appropriate deed restriction will be required if property meets either of the foregoing conditions.</i></p>	
<p>2. FLOODPLAIN Property <input type="checkbox"/> is <input type="checkbox"/> is not located within the 100-year floodplain (Zones A and V).</p> <p><i>Note: Flood insurance may be required.</i></p>	
<p>3. AIRPORT RUNWAY CLEAR ZONES (24 CFR 51D) Property <input type="checkbox"/> is <input type="checkbox"/> is not located within boundary of runway zone.</p> <p>If "yes",</p> <ul style="list-style-type: none"> • Has the airport operator declined to acquire the property? <input type="checkbox"/> yes <input type="checkbox"/> no • A signed disclaimer is required (24 CFR Part 51D). 	
<p>4. SUMMARY Additional actions <input type="checkbox"/> are <input type="checkbox"/> are not required on the basis of the findings above. If additional actions are required, describe them in an attachment.</p>	
<p>NOTE: OTHER ENVIRONMENTAL STATUES, EXECUTIVE ORDERS AND AUTHORITIES The remaining statutes and authorities cited at 24 CFR 50.4 do not require compliance because they are not relevant to property disposition actions which do not involve new construction.</p>	
Preparer: _____	Supervisor: _____
Title: _____ Date: _____	Title: _____ Date: _____